

FAST ACTUATION SYSTEM

64

ZERO POINT QUICK CHANGE DEVICES / ACCESSORIES / FAST ACTUATION SYSTEM

Workpieces can be clamped firmly by rotating the clamping lever 180 degrees from right to left



Model: M-52x52AS

- 1 set
- Weight: 0.49 kg / set

Model: M-96x96AS

- 1 set
- Weight: 0.63 kg / set