

Optional Accessories

for Zero Point Quick Change Devices

60

ZERO POINT QUICK CHANGE DEVICES / ACCESSORIES

Pull Studs

Can be adopted onto vises or workpieces to use together with any Quick Change Device.





Model: M-52x52PS

- 4 pcs / set
- Weight: 0.16 kg / set



Model: M-96x96PS

- 4 pcs / set
- Weight: 0.28 kg / set



Spacer Studs

Improve the machining accessibility of edges or angles by making a through space between workpieces and Quick Change Devices.





Model: M-52x52SS

- 4 pcs / set
- Weight: 0.27 kg / set



Model: M-96x96SS

- 4 pcs / set
- Weight: 0.4 kg / set



Applications:

