

Optional Accessories

for Zero Point Quick Change Devices

Pull Studs

Can be adopted onto vises or workpieces to use together with any Quick Change Device.





Model: M-52x52PS

- 4 pcs / set
- Weight: 0.16 kg / set



Model: M-96x96PS

- 4 pcs / set
- Weight: 0.28 kg / set



Spacer Studs

Improve the machining accessibility of edges or angles by making a through space between workpieces and Quick Change Devices.





Model: M-52x52SS

- 4 pcs / set
- Weight: 0.27 kg / set







Model: M-96x96SS

- 4 pcs / set
- Weight: 0.4 kg / set



Applications:



Optional Accessories

for Zero Point Quick Change Devices

Cover Plugs - Plastic

Model: M-52x52CPP

- 4 pcs / set
- Weight: 0.01 kg / set



Model: M-96x96CPP

- 4 pcs / set
- Weight: 0.02 kg / set



Cover Plugs - Steel

Model: M-52x52CPS

- 4 pcs / set
- Weight: 0.10 kg / set



Model: M-96x96CPS

- 4 pcs / set
- Weight: 0.16 kg / set



Cover Plug with hook

Model: M-52x52H

- 2 pcs / set
- Weight: 0.18 kg / set

Model: M-96x96H

- 2 pcs / set
- Weight: 0.32 kg / set



Cover Plug Remover

for M-52x52 and M-96x96

- 1 pc
- Weight: 0.11 kg

